


ContactScope
3.CS210P01.V1A.E/A.24
1038075A

10



Input/Output
Machine interface
For GAP/Crash/Dress signal
Sub-D socket 37-way

Cable
7-way, 10m
3.710BS
1012656A

20

Optional sensors:

- 30a
- 30b
- 30c with 31

